# Place No. 06 Chirrita Station



Chirrita Station buildings 2012: stone remains of early homestead in foreground, with later structures in middle ground and foreground

LOCATION	
Name of Place	Chirrita Station
Other Name (1)	Maitland River Run
Other Name (2)	Cherratta Station, Chirritta Station
Location/Address	
Street Name	Cherratta Road
Suburb/Town	Close to Maitland River
Other Locational Descriptor	mE 479670 mN7676538
	Longitutde 116.8044 Latitude -21.0118

### **OWNERSHIP & LAND DESCRIPTION**

Owner	Address	Phone/fax	Status	Item No.
Ieramugadu Pastoral Company	1 Padbury Street Roebourne			
Reserve No.	Lot/Location No.	Plan/Diagram	Vol/Folio	Item No.

LISTING & ASSESSMENT	
HCWA Reference Number	8664
State Register of Heritage Places:(Y/N)	No
Classified by the National Trust (Y/N)	No
Register of the National Estate (Y/N)	No
Local Town Planning Scheme (Y/N)	
Management Category	В

DESCRIPTION	
Construction Date (1)	
Construction Date (2)	
Site Type (Place Type)	Other Structure

Use(s) of Place	
Original	FARMING/PASTORAL:
	Homestead
	Servants' Quarters/Shearers' Quarters
	Shed
	Kitchen
	Stockyard
	Outstation
	Other
Present	FARMING/PASTORAL:
	Residences
	Sheds
	Kitchen
	Stockyard
	Other
Other	Pastoral station - out station of Mount Welcome Station
Construction Materials:	
Walls	9. STONE
	904 Local Stone
	6. METAL
	606 Corrugated Iron
Roof	6. METAL
	606 Corrugated Iron
Condition	Poor
Integrity (how much of the original fabric	The earlier buildings are largely in a ruined and disused
is intact?):	condition
Physical Description	

## Physical Description

The station homestead complex is comprised of late 19<sup>th</sup> and early 20<sup>th</sup> century structures combined with a range of late 20<sup>th</sup> and early 21<sup>st</sup> century residential buildings.

The earliest homestead buildings are located around a small stony outcrop. This includes the ruined remains of a stone-built homestead of three rooms, the verandah of which once looked over the plain towards the north and east. Another square stone walled building has complete walls, although no roof. In the immediate vicinity are six buildings predominantly made of corrugated iron cladding on wooden frames, with concrete floors. These were residences, quarters, kitchen, engine room, and working areas. They are still used in some instances as residences.

The shearing shed on the other side of the outcrop is of corrugated iron cladding on a metal and wooden frame, with concrete and raised timber floors. It contains the remains of holding pens, shearing equipment, wool carding tables, engine rooms and wool pens. A nearby stone building may have served as an earlier engine room.

On the road into the homestead are the remains of the early woolshed, which appear to relate to very early uses of the station, being made of local stone. This complex includes a low wall across the ridge to form part of a stock containment area (similar to that at Old Woodbrook Station). The main building is the shearing shed with surrounding stone walls (similar to Springs Station and Inthanoona Station). Some flagstones remain, as well as wooden posts at the gates and building walls.

#### **History**

Chirrita Station was one of the early pastoral stations in the region, taken up in approximately 1865 by Norman McLeod (Donald Norman). His son, Donald, managed the station until its sale to A C Gillam. It is unclear when the station was sold to Mr Gillam, but he certainly owned it in 1889, when an article records him sending 500 sheep on the Australind, bound for the Singapore market. <sup>1</sup>

The Withnell brothers (part of the Withnell family who were early settlers in the Roebourne area)

bought the station from Gillam in roughly 1903.<sup>2</sup>

The Stove Brothers purchased the station from Gillam in the early 1920s. The Stove brothers also owned Mount Welcome (HCWA Reference number 2343) and Cooya Pooya Station (HCWA Reference number 3376) around this time, <sup>3</sup> thus linking Chirrita Station to Mount Welcome Station. The links with Mt Welcome continue into the present as the station is now part of Mt Welcome Station and cattle are run on the station.

Today the station continues to be an important place, as the site of the old homestead is home to a community of people.

#### Archaeology

There is significant archaeological potential for remains associated with the sheep and later cattle industry at Chirrita Station. The sequence of 19<sup>th</sup> and 20<sup>th</sup> century station buildings records the history of architecture, vernacular design and changes in stations and technology over 150 years. The contribution and realities of station life for Aboriginal people could also be reflected in the material remains as well as local memories.

SIGNIFICANCE	
Historic theme (s)	3. OCCUPATIONS
	301 Grazing, pastoralism & dairying
Statement of Significance:	

Chirrita Station has historic significance as one of the early pastoral stations in the Shire of Roebourne (c1865) with evidence of changes in station life in the North West over time. The station buildings are a mix of the stone remains of the original structures - homestead buildings, and wool shed and yards - with post 1950s additions at the homestead complex. There is clear research potential to explore over 150 years of station life. The station precinct has aesthetic significance as it is set within a landscape of rolling hills and ridge lines with views across the Maitland River floodplain. The station is part of a tradition of stock raising that continues into the present.

ASSOCIATIONS	
Architect/Designer (1)	
Other Associated Person(s)	Norman McLeod, original owner
	Withnell family
	Ngarluma people

#### References

*The Western Australian* 29<sup>th</sup> March 1889, Latest from the North-West, <a href="http://trove.nla.gov.au/ndp/del/article/66092688">http://trove.nla.gov.au/ndp/del/article/66092688</a>?

Heritage Council of Western Australia, Register of Heritage Places Assessment Documentation, Mount Welcome House

Taylor, N.E.W, 1986, Yeera-Muk-A-Doo, A Social history of the First Settlement of North West Australia told through the Withnell and Hancock Families 1861-90.

MHI 1996	Assessment undertaken, Place Record Form created
MHI Review 2012	Entry updated



Chirrita Homestead 2012: stone structure overlooking shearing shed



Cherratta Homestead 1900 Courtesy Shire of Roebourne Local History Collection, 2005.351

The Western Australian 29<sup>th</sup> March 1889, Latest from the North-West, http://trove.nla.gov.au/ndp/del/article/66092688?
Taylor, N.E.W, 1986, Yeera-Muk-A-Doo, p 234
Heritage Council of Western Australia, Register of Heritage Places Assessment Documentation, Mount Welcome House, p5-6